

What respiratory protective devices require fit testing?

All tight fitting masks (negative and positive pressure) must be fit tested to the wearer. Positive pressure masks are fit tested under negative pressure.

Loose fitting headtops connected to a PAPR blower do not require fit testing.

AS/NZS 1715 and ISO 16975-3 recommend fit testing is to be conducted annually.

Fit testing required

Example of, but not limited to, styles and combinations that require fit testing



NOTE: Full face masks must be quantitatively fit tested

Fit testing NOT required

Examples of, but not limited to, loose fitting headtops and blower combinations that DO NOT require fit testing



3M Australia Ptv Ltd Personal Safety Division Bldg A, 1 Rivett Road North Ryde NSW 2113

TechAssist Helpline 1800 024 464 Customer Service 1300 363 565 techassist@mmm.com www.3M.com/au/ppesafety Web

3M New Zealand Ltd **Personal Safety Division** 94 Apollo Drive, Rosedale Auckland 0632

TechAssist Helpline 0800 364 357 Customer Service 0800 252 627

www.3M.com/nz/ppesafety

3M is a trademark of 3M Company. Please recycle. Printed in Australia © 3M 2019. All rights reserved. AV011491758